

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,095,261 B2
APPLICATION NO. : 10/840015
DATED : August 22, 2006
INVENTOR(S) : Adrian J. Drexler et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:


TITLE page, (75) Inventors: change "Seong-hoon" to --Seong-Hoon--.
TITLE page, (56) References Cited: In "6,556,489; 6,586,979; 6,727,734; 6,735,148;
6,737,897; 6,759,883; 6,774,687; 6,781,861; 6,803,826; 6,850,107" change
"B1" to --B2--.
Column 3, line 38, change "tck" to -- t_{ck} --.
Column 7, line 47, change "tck" to -- t_{ck} --.
Claim 12, column 10, replace 22 lines of text from
"a second multiplexer" through "through the same number of delay elements."

Replace with:

-- In response to receiving an indication, means for continuing to generate
said synchronized clock signal in response to said delayed fed back
synchronized clock signal independent of said reference signal. --

Signed and Sealed this

Sixteenth Day of January, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office